

Radon test result report for:**MIDLAND CSD
MS/HS BUILDING**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11903217	A104	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.7 ± 0.3	2025-02-19
11903218	A104-2	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.7 ± 0.4	2025-02-19
11903219	A104-3	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.5 ± 0.3	2025-02-19
11903230	A106	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.8 ± 0.4	2025-02-19
11903231	A107	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.4 ± 0.3	2025-02-19
11903232	A107 D	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	2.1 ± 0.4	2025-02-19
11903215	A108	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.7 ± 0.3	2025-02-19
11903233	A109	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.6 ± 0.4	2025-02-19
11903225	A111	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.7 ± 0.3	2025-02-19
11903227	A111-2 D	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.5 ± 0.3	2025-02-19
11903228	A112	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.2 ± 0.3	2025-02-19
11903229	A112-2	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	0.9 ± 0.3	2025-02-19
11903204	A124	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.0 ± 0.3	2025-02-19
11903205	A124-2	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.5 ± 0.3	2025-02-19
11903206	A124-3	2025-02-10 @ 11:00 am	2025-02-14 @ 11:00 am	0.8 ± 0.3	2025-02-19
11903175	A136	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.7 ± 0.4	2025-02-19
11903182	A138	2025-02-10 @ 9:00 am	2025-02-14 @ 7:00 am	1.9 ± 0.4	2025-02-19
11903234	A139	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.2 ± 0.3	2025-02-19
11903177	A141	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.0 ± 0.3	2025-02-19
11903176	A144	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	0.7 ± 0.3	2025-02-19
11903180	A144-2 D	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	0.7 ± 0.3	2025-02-19
11903181	A146	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.0 ± 0.3	2025-02-19
11903179	A147	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	0.9 ± 0.3	2025-02-19
11903169	A151	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	1.0 ± 0.3	2025-02-19
11903170	A152	2025-02-10 @ 9:00 am	2025-02-14 @ 9:00 am	0.7 ± 0.3	2025-02-19
11903171	A152-2 D	2025-02-10 @ 9:00 am	2025-02-14 @ 9:00 am	0.9 ± 0.3	2025-02-19
11903168	A153	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	< 0.3	2025-02-19
11903173	A154	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.7 ± 0.4	2025-02-19
11903174	A154-2 D	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.5 ± 0.4	2025-02-19
11903165	A159	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	1.3 ± 0.3	2025-02-19
11903213	A160	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	0.7 ± 0.3	2025-02-19
11903214	A160-2 D	2025-02-10 @ 8:00 am	2025-02-14 @ 12:00 am	0.6 ± 0.3	2025-02-19
11903212	A161	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	0.8 ± 0.3	2025-02-19
11903211	A163	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	0.8 ± 0.3	2025-02-19
11903223	B1	2025-02-10 @ 7:00 am	2025-02-14 @ 8:00 am	???? IA8	2025-02-19
11903183	B103	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.0 ± 0.3	2025-02-19
11903184	B103-2	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.2 ± 0.3	2025-02-19

February 20, 2025

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
MIDLAND CSD
MS/HS BUILDING

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
1903185	B103-3	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.3 ± 0.3	2025-02-1
1903186	B106	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.8 ± 0.4	2025-02-1
1903187	B109	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	2.1 ± 0.4	2025-02-1
1903188	B109-2	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	2.1 ± 0.4	2025-02-1
1903189	B109-3	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	2.3 ± 0.4	2025-02-1
1903190	B111	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	2.0 ± 0.4	2025-02-1
1903191	B113	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.5 ± 0.3	2025-02-1
1903193	B124	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.8 ± 0.4	2025-02-1
1903194	B126	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	3.3 ± 0.4	2025-02-1
1903195	B132 BLEACHERS PULLED IN EVENING OF	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.6 ± 0.3	2025-02-1
1903196	B132-2 BLEACHERS PULLED IN EVENING	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.5 ± 0.4	2025-02-1
1903197	B132-3 BLEACHERS PULLED IN EVENING	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	1.4 ± 0.4	2025-02-1
1903198	B132-4 BLEACHERS PULLED IN EVENING	2025-02-10 @ 12:00 am	2025-02-14 @ 10:00 am	1.7 ± 0.3	2025-02-1
1903222	B2	2025-02-10 @ 7:00 am	2025-02-14 @ 8:00 am	5.0 ± 0.5	2025-02-1
1903221	B3	2025-02-10 @ 7:00 am	2025-02-14 @ 8:00 am	6.8 ± 0.5	2025-02-1
1903220	B4	2025-02-10 @ 7:00 am	2025-02-14 @ 8:00 am	9.3 ± 0.7	2025-02-1
1903224	B5 SMALL AMOUNT OF CHARCOAL LEAKAGE	2025-02-10 @ 7:00 am	2025-02-14 @ 8:00 am	4.8 ± 0.5	2025-02-1
1903207	BB	2025-02-10 @ 11:00 am	2025-02-14 @ 7:00 am	1.6 ± 0.4	2025-02-1
1903216	BLK	2025-02-10 @ 8:00 am	2025-02-14 @ 7:00 am	< 0.3	2025-02-1
1903172	BLK	2025-02-10 @ 8:00 am	2025-02-14 @ 7:00 am	< 0.3	2025-02-1
1903226	BLK	2025-02-10 @ 7:00 am	2025-02-14 @ 7:00 am	< 0.3	2025-02-1
1903199	C107 BLEACHERS PULLED IN SHOULD NOT	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.3 ± 0.3	2025-02-1
1903200	C107-2 BLEACHERS PULLED IN SHOULD N	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.2 ± 0.4	2025-02-1
1903201	C107-3	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.3 ± 0.3	2025-02-1
1903202	C107-4	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.5 ± 0.4	2025-02-1
1903203	C107-5	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	1.5 ± 0.3	2025-02-1
1903210	EBERHARD	2025-02-10 @ 8:00 am	2025-02-14 @ 11:00 am	1.4 ± 0.4	2025-02-1
1903166	ES2	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	0.9 ± 0.3	2025-02-1
1903167	ES2	2025-02-10 @ 8:00 am	2025-02-14 @ 9:00 am	0.9 ± 0.3	2025-02-1
1903192	PE OFFICE	2025-02-10 @ 10:00 am	2025-02-14 @ 10:00 am	4.6 ± 0.5	2025-02-1
1903208	PPF	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	3.1 ± 0.4	2025-02-1
1903209	PPF-2	2025-02-10 @ 11:00 am	2025-02-14 @ 10:00 am	3.2 ± 0.4	2025-02-1

February 20, 2025

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

**MIDLAND CSD
MS/HS BUILDING**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11903178	A148	2025-02-10 @ 9:00 am	2025-02-14 @ 10:00 am	1.1 ± 0.3	2025-02-19

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498